



Hindustan
Motors
Limited

AUTOMOBILE DIVISION

Hindmotor, Hooghly, West Bengal - 712 233, India

Phones : (033) 663-1036/1550 Telex : 021-4146/4187, Fax : 91-33-663-1355

Ref: GEN/FM/ (411

May 13, 1988

Mr. Jayprakash Sathe
Katalist Consult. Pvt. Ltd.
1187/25 Ghole Road,
Shivajinagar,
Pune-411005.

Ref: Your demonstration of Fabricare Roof Top Safety
provision (Crawling Board) in our premises.

Dear Sir;

This is in context of your demonatration and subsequent usage of
Crawling Boards in our Factory Premises. It may noted that we
have successfully implemented the same and presentiy no work on
Roof Top is being done without Crawling Board supplied by you.


In the meantime, we have brought the same to notice of the Chief
Inspector of the Factories, Government of West Bengal. He is
apparently very much interested in the provisions being supplied
by you and is keen for personal observation of the cassette being
provided by you: It is likely that he may prescribe the same
method to be observed by other industries as improved safety is
the Call of the Day.

You are therefore, requested to kindly contact Mr. R.K. Ganguly,
Chief Inspector of Factories, Govt. of West Bengal, New
Secretariat Building, Calcutta-700 001, Phone No. (033) 210-3270.
This may be treated as urgent as it has been personally requested
to us by the Chief Inspector of Factories, Govt. of West Bengal.

A line of confirmation from your end to the undersigned
conforming to the same will be appreciated.

Thanking you,

yours faithfully,
for Hindustan Motors Ltd.


(D. Munshi)
Factory Manager

cc. The Chief Inspector of Factories
Govt. of West Bengal
New Secretariat Building
Calcutta-700 001.

⑤

No. ACC/MSK/82/ 98400 /D-4,
Factory Inspection Office,
Commerce Centre, Tardeo,
Bombay-34.

Dated :- 11/1/82

C I R C U L A R . N o . 1 1

In the recent past number of accidents have occurred due to fall of persons through fragile roof resulting into loss of life of number of person. All the inspectors are informed that in order to minimise such accidents, provision of Rule 73 (F) of the Maharashtra Factories Rules, 1963 needs to be strictly followed by the managements. Inspectors are informed that they should ensure that factory management follow work permit system and use safety ladders which are now available in market. These matters should be check up during visit to the factories and suitable remarks in the Inspection Book should be passed by them.

W. N. Kholkute
(V. N. KHOLKUTE).
Chief Inspector of Factories
Maharashtra State,
Bombay.